

General Environmental Incident Summary

Incident: 5263 **Date/Time Notice:** 11/10/2016 **DEM Incident No:**

Responsible Party: Fargo Electric Construction

Date Incident: 11/10/2016 **Time Incident:** 1000 **Duration:**

County: Cass **Twp:** 139 **Rng:** 49 **Sec:** 10 **Qtr:**

Lat: 46.87577 **Long:** -96.84192 **Method:** Interpolation from map

Location Description: Main Ave and southbound I-94 Ramp

Submitted By: Hunter Hubrig

Affiliation: Fargo Cass Public Health

Address: 4630 15th Ave N

City: Fargo

State: ND

Zip:

Received By:

Contact Person:

325 39th St N
Fargo, ND 58103

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 15.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Truck and trailer flipped merging onto ramp. 20 gallon tank was on side straddling the road with a pencil sized puncture.

Risk Evaluation:

Most of spill contained to roadway. Small amount leaked to soil along roadside. Was properly cleaned up and disposed of.

of Fatalities:

of Injuries:

Affected Medium: 09 - other

Potential Environmental Impacts:

None. No drains nearby.

Action Taken or Planned:

Fargo Fire Department responded. Positioned tank upright to stop leak and cleaned up site with floor dry.

Wastes Disposal Location: Fargo Landfill

Agencies Involved: State Highway Patrol, Local Fire Department, Local Law Enforcement

Updates

Date: 11/14/2016 ***Status:*** Reviewed - No Action Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Spoke to Hunter Hubrig with Fargo Public Health who had visited the site. Area has been cleaned up, and there is no evidence of remaining impacts. No follow-up is required.